

Test Report



Sample Information	
Item Description:	Underwire /PET Coated
Colour:	N/A
Test Methods:	ISO, AATCC & ASTM

Test Method	Requirement	Conformity
» BRA WIRE RECOVERY	60% minimum	Pass
» FREE NICKEL CONTENT(QUALITATIVE)	Can not be present	Pass
» RESISTANCE TO RUST & CORROSION	No corrosion present (Grade 10)	Pass



Samples for testing has been selected according to the Random Sampling Technique where each sample has an equal probability of being chosen. There is a possibility that the sample does not represent the population as a whole due to any random variation (Sampling Error). All tests are performed only by certified laboratory technicians.

-

